DATE OF INSPECTION: May 5, 2015

U&O INSPECTION REPORT

U&O NAME: Sesko U&O START: END:

USE: Derelict Pontoons LEGAL: Sec 14; Twp 24 N; Rng 1E

LAT: LONG:

NUMBER: No U&O Number Assigned

ADDRESS: Thompson Drive, Bremerton, WA;

ADJACENT TERRESTRIAL PARCEL: 3711-000-001-0409

PHONE NUMBER: N/A

Contact made for inspection: No

AREA PERCENTAGE

% WATER DEPENDENT % NON-WATER DEPENDENT

IMPROVEMENTS ON STATE-OWNED AREA

TYPE	CONDITION	DESCRIPTION
Ballast Tanks	Poor	two metal ballast tanks; 32-ft long by 16-ft in diameter; The tanks were utilized to adjust submarine depth by increasing ballast.

INSPECTOR'S Remarks and Recommendations (amendment, maintenance, liability etc…)

Recent contact was made with the Sesko property Trustees. They are proposing to remove the two tanks. The site visit was to assess the current condition of the tanks if they ask DNR to take the lead on removal. The site inspection was conducted on May 5, 2015 at 2:23 PM during a low tide.

Generally the metal seems sound. However, the two tanks are clearly taking on water. There was a small stream of water coming out of one tank. The other tank had a slow drip indicating that was also taking on water. Neither tank is buried in the beach sediment.

INSPECTOR: Lindie Schmidt TITLE: Natural Resource Specialist II

DATE OF INSPECTION: May 5, 2015

Diagram Below, the location of existing structures showing alignment and dimensions in relation to leased area.



2012 Aerial photo from the Kitsap County Assessor webpage showing Kitsap County Parcel 3711-000-001-0409 outlined. The pontoons can be seen waterward of the parcel.

INSPECTOR: Lindie Schmidt TITLE: Natural Resource Specialist II

DATE OF INSPECTION: May 5, 2015

Foreground, ballast tank with white paint. Background ballast tank with red paint.

INSPECTOR: Lindie Schmidt TITLE: Natural Resource Specialist II



Water observed coming out of the ballast tank with red paint.



Water dripping out of the ballast tank with white paint.

Ballast tank can be seen resting on the beach surface.